METHOD FOR REMOVING OXIDE FROM CRACKS IN TURBINE COMPONENTS

ABSTRACT OF THE DISCLOSURE

A method for removing an oxide material from a crack in a substrate, the method includes: applying a slurry paste comprising a fluoride salt to the crack; heating the slurry paste and the crack to at least a melting point of the fluoride salt to form a reaction product; and removing the reaction product.